



**humimeter.com<sup>®</sup>**

by Schaller Messtechnik

# User manual





Moisture meter for determining  
water content of biomass

## humimeter BMA



version 2.2



© Schaller GmbH  
2016

## Design of the device



# Operation

1. Put the empty measuring box into the humimeter BMA correctly. Make sure to hook in the aluminium part of the measuring box centrally into the plastic brackets of the drawer.
2. Close the drawer and push it down (normally this is effected automatically).
3. Plug in the round plug of the delivered power supply unit at the humimeter BMA and tighten it.
4. Plug in the power supply unit into a Schuko socket (230VAC).
5. After plugging in, the humimeter BMA switches on automatically. If not, switch on the instrument by pressing the  button for 3 seconds.
6. The query for a self calibration „Reinitialize?“ shows up on your display. Accept by pressing the  button.
7. The self calibration has finished when the display shows the measuring window.
8. If the self calibration cannot be completed successfully, please read through page 12, header fault correction.













## Measuring procedure

1. Open the drawer of the humimeter BMA and take out the measuring box. For that, lift the box and then pull it out.
2. Completely fill up the measuring box with the material to measure. For that you must use the delivered bucket.
3. Wipe off the material at the upper edge of the box evenly.
4. Put the filled measuring box into the drawer correctly and close it.
5. Select the right product (calibration curve) using the arrow keys.
6. Press the Start push button. The measurement will start automatically. During the measurement, the LED is blinking in blue and the display shows the symbols for an ongoing measurement (see picture).
7. After the measuring procedure is completed, the LED is shining in blue constantly and the measuring values are shown on the display.
8. If desired the measuring values can be saved now. For that, please follow the instructions on the next page.
9. Open the drawer and carefully remove the measuring box.
10. Empty the measuring box completely.



## Saving of measuring values


1. If desired the measuring values can be saved in the store menu by pressing the  button ( button). The storage was successful when the number in front of the  symbol increases. To reach the store menu please press the left button () as long as the symbol  appears.
2. To name the saved results press the  button.
3. Here you can name the measuring series using numbers and letters. For numbers press  (0..9) and for letters  (A..Z).
4. After entering the name, confirm by pressing  (Enter). Now the saving is completed.



**name of series**  
**water content (average)**  
**temperature (average)**  
**atro weight / m³ [kg/m³]**  
**(average) optionally**  
**bulk density [kg/m³]**  
**(average) optionally**


**Note:** The accuracy of a measurement can be improved by performing several measurements (3) with the same sample and calculating the average of them. If the individual measuring values are stored on the BMA, the device calculates the average automatically.


## Printing hot key *(only with optional integrated printer)*

Pressing the second button from left () the last saved measuring series is printed.

Note: This means that the last saved value is printed, and not the last measured value.

## List of calibration curves

Pressing one of the arrow keys in the measuring window for at least 3 seconds, a list of all available calibration curves will appear. Select your desired product using the arrow keys and confirm by pressing .



## Calibration curves

name (material)	description	dimensions	measuring range
<b>Woodchips</b>	forest wood chips (or similar)	P16 - P45	5 - 70 %
<b>Coarse ch.</b>	wood chips with less fines	P45	5 - 70 %
<b>Industr. WC</b>	wood chips without fines	P45 - P63	5 - 70 %
<b>Barks</b>	barks	P31 - P45	5 - 70 %
<b>Pellets</b>	wooden pellets	Ø 6 mm	5 - 14 %
<b>Miscanthus</b>	chopped miscanthus	similar P16	5 - 35 %
<b>Shavings</b>	shavings		5 - 45 %
<b>Sawdust</b>	sawdust		5 - 70 %
<b>Corn cob</b>	corn cobs (chopped or total)		5 - 40 %
<b>Empty 1</b>	for special sorts (calibration by Schaller GmbH)		
<b>Reference</b>	for testing humimeter BMA. Not suited for measuring!		

## Determination of the material reference moisture

The humimeter BMA determines the water content, this is the moisture related to the total mass (wet base):

$$\%WG = \frac{M_n - M_t}{M_n} \times 100$$

$M_n$ : Mass with average moisture content

$M_t$ : Mass of the dried sample

%WG: water content (according to norm EN ISO 18134-2)

## Definition of wood chips classes (EN ISO 17225-1)

The stated numbers refer to the particle size that goes through round gaps of the corresponding diameters (e.g. P16: 16 mm).

- **P16** minimum 75% of mass is between 3.15 and 16 mm
- **P31** minimum 75% of mass is between 8 and 31,5 mm
- **P45** minimum 75% of mass is between 8 and 45 mm
- **P63** minimum 75% of mass is between 8 and 63 mm

# Selection of the right calibration curve for wood chips

**The right calibration curve depends on the size of wood chips and especially on the content of fines.**

*We gladly assist you with the selection of the right calibration curve. Take a picture placing a measuring tape next to your wood chips and send it to [support@schaller-gmbh.at](mailto:support@schaller-gmbh.at). You will get a recommendation promptly.*

If you are not sure which calibration curve is the best suited for your material, it is recommended to carry out a reference measurement by kiln-drying (EN 14774).

Below you can find instructions and pictures for the different calibration curves. For further pictures on our website, please just click on the QR code.



## **1.) Wood chips**

This calibration curve is used for forest wood chips (P16 to P45) and for similar wood chips types with coarse and a lot of fine fraction.

Fine fraction mainly originates from barks and small branches.

If the material doesn't contain small parts, one of the two other wood chips calibration curves has to be taken.

This calibration curve also has to be taken for wood chips from short rotation forestry harvested by a field chopper.

## **2.) Coarse chips**

For coarse chips as well as finer wood chips with few fine fraction of wood chips classes P31 up to P63.

This can be wood chips from sawmill residues or coarse forest wood chips with few fines.

## **3.) Industrial wood chips**

This calibration curve is suited for wood chips without fines of classes P45 to P63.

Such wood chips for example produce sawmills chipping cutting residues (without barks).

## Example pictures for calibration curve wood chips:



## Example pictures for calibration curve coarse wood chips:










## Example pictures for calibration curve industrial wood chips:















## Menu level overview

## Keypad symbols

### Measuring window:

-  Rolling menu
-  On/Off
-  Switch upper
-  Switch lower
-  Save
-  Watch saved data
-  Add suppliers data

### Menu:

-  Enter
-  Switch upper
-  Switch lower
-  Back
-  Enter numbers
-  Enter letters
-  Next or right
-  Left
-  Yes
-  No
-  Shift
-  OK




Type selection menu

- Next calibration curve
- Last calibration curve
- Power off (3 sec.)



Store menu

- Watch last saved data
- Save new value
- Printing hot key



Main menu

- Switch lower
- Switch upper
- Open the menu / Enter

## Overview main menu

<i>Edit logs</i>	<i>Options</i>
Manual logs	Date / Time
Clear logs	Datalog Time
	Language
<i>Print logs</i>	Unlock
Last log	°C / °F
All logs	o Userlevel
Clear logs	BL On time
	Auto Off Time
<i>Send logs</i>	Calibrate
Manual logs	Materialcalib.
Clear logs	Adjust
<i>Options</i>	Password
	Reset
<i>Status</i>	SN.
	Logo
	Admin

## Transfer saved data to the PC

***(only possible with USB data interface module)***


To send your saved logs to the PC, connect the humimeter device to your PC using the USB cable that was delivered with your device. Carefully loosen the protection cap on your humimeter and plug in the USB miniB connector. The bigger connector has to be connected to a USB slot on your PC.







Start the LogMemorizer software on your PC and switch on your humimeter BMA.

The data transfer can be started on your humimeter or on the software:

Starting the data transfer on the humimeter:




Press the  key until you reach the menu (see image on the right). Then choose „Send Logs“ and confirm by pressing the  key. Now choose „Manual Logs“ and confirm with  again. All saved logs will be sent to your PC now.



Starting the data transfer on your PC:


Press the button „remote control“ in the LogMemorizer software. A drop-down menu with several options opens (see image below).



For transferring the data you can select „Import last manual log“ (the last saved measuring series is transferred) or „Import all manual logs“ (all saved logs are transferred).

If you click on one of these menu items, the transfer starts immediately.



For the basic adjustments of the software please look through the instructions on the LogMemorizer USB flash drive.




## Print saved data

***(only possible with optional integrated printer)***

To print out your saved data, send a print job at your humimeter device.



For that press the  button until you reach the menu (see image on the right). Select the menu item „Print logs“ and confirm by pressing .

Now you can select if you want to print the last saved measuring series or all saved measuring series (logs).

Confirm by pressing  again. The selected logs are printed out now.

*To save paper, please think of clearing the data storage regularly.*

If the printing has been started successfully, the printer begins to print out the logs immediately. The green LED shows the correct operation.



## Changing the paper roll

For exchanging a blank thermo paper roll, lift up the clip until the cover opens (see picture).

Remove the blank roll.

Put a new opened roll into the printer, ensuring that the paper comes out to the fore (see picture).

While closing the cover, hold the beginning of the paper tightly to prevent the paper from wrinkling.




Now the printer is ready for use again.



## Several functions

### Setting the clock



2 times  -> Options -> Date / Time

Enter date and time using the  button. Pressing the  button the cursor shifts to the next place. Pressing the  button (OK) your entry will be saved.

*Info: If the power supply unit is unplugged the clock stands still!*

### Unlocking the instrument (Super User)

2 times  - Options – Unlock

Enter the 4-digit password using the button  (standard is the 4-digit serial number) and confirm by pressing .

### Online print

2 times  -> Options -> o Online Print

*For choosing that menu item you have to unlock your BMA first!*

If you have activated that function, your BMA will print the current measuring value after pressing save button immediately.

## LED signals

Shining in blue

device is ready for operation

Blinking in blue

ongoing measurement

Blinking in red

failure

Possible reasons for failure (red blinking LED):

- Drawer has not been closed correctly
- Measuring box is missing resp. empty
- Wrong positioning of measuring box
- Overloaded motor for compression

⇒ *The failure can be confirmed by pressing the START push button!*

# Definition of important units for wood chips accounting

name	unity	explanation
water content [WC]	[ % ]	<p>Water content is called the ratio of water to the total wood mass as a percentage <math>[kg/kg] \times 100</math>. This unit is used in the <b>Biomass- Norm for wood chips</b>:</p> $WC = \frac{m_{water}}{m_{total}} \times 100 = \frac{m_{water}}{m_{dry\ mass} + m_{water}} \times 100$ <p>1000 kg wood chips with 40 % WC =&gt; 400 kg water &amp; 600 kg wood chips</p>
wood moisture [u]	[ % ]	<p>Wood moisture is called the ratio of water to the dry wood mass as a percentage <math>[kg/kg] \times 100</math>. This unit is used in the <b>General Wood Norm for split logs</b>:</p> $u = \frac{m_{water}}{m_{dry\ mass}} \times 100$ <p>but <math>m_{water} = m_{total} - m_{kiln-dry\ weight}</math></p> <p>1000 kg split logs with 40 % WC =&gt; 400 kg water &amp; 600 kg split logs 400 kg water &amp; 600 kg split logs =&gt; 66,7 % wood moisture</p>

name	unity	explanation
dry weight (atro weight)	[ kg ]	<p>Dry weight (atro weight) is called the weight of wood chips without the included water. It is also called <b>atro tons</b>:</p> $dry\ (atro) = m_{total} \times (100 - WC) / 100$ <p><math>m_{total}</math> : weight of delivered wood chips WC: water content (e.g. from humimeter BMA)</p> <p>1000 kg wood chips with 40 % WC =&gt; 600 kg wood chips <b>dry (atro)</b></p>

name	unity	explanation
bulk density	$\left[ \frac{kg}{m^3} \right]$	<p><b>Weight of wood chips per cubic metre</b> (inclusive the water in the wood chips)</p> $bulk\ density = \frac{m_{total}}{V_{total}}$ <p>1000 kg wood chips have a volume of 3,33 m<sup>3</sup> =&gt; 300 <math>\frac{kg}{m^3}</math></p>
$\frac{dry\ weight}{m^3}$ $\frac{atro\ weight}{m^3}$	$\left[ \frac{kg}{m^3} \right]$	<p><b>Weight of the wood chips without any water per cubic metre</b></p> $\frac{dry\ weight}{m^3} = \frac{bulk\ density \times (100 - WC)}{100}$ <p>300 <math>\frac{kg}{m^3}</math> bulk density with 40 % WC =&gt; 180 <math>\frac{kg}{m^3}</math> <math>\left[ \frac{dry\ weight}{cubic\ metre} \right]</math></p>

## **Notes for bulk density and bone dry weight (atro) / m<sup>3</sup>**

For determining the bulk density according to the norm EN14961 a round bucket is used. As the humimeter BMA uses a rectangular measuring box, we have entered a compensation factor in the device. This compensation factor has been optimised for wood chips and therefore can differ when measuring other material types. The bulk density of biomass material during transport can change considerably (compacting), when measuring the volume a material cone has to be considered.

An eventual discrepancy of the bulk density directly influences the displayed dry weight /m<sup>3</sup>.

## **Notes for comparison measurement with drying oven**

The humimeter BMA uses a much higher sample quantity than the drying oven (12-fold to 20-fold quantity of kiln-drying method). Furthermore, to determine a more accurate average moisture value in case of inhomogeneous material, the humimeter BMA enables a large number of measurements within a short time. Considering a sampling error due to the considerably smaller sample quantity as well as the content of volatile matters, resin etc. (that are not water), the kiln-drying method will practically reach an accuracy of approx. +/- 3%. Therefore, if the measuring values of these two very different methods of determining the water content are compared, differences of +/- 3% can be considered to be normal.

In standard EN ISO 18134-2 is declared, that these drying oven method provides no absolute values. There you receive values which are comparable only.

## **Exemption from liability**

For miss-readings and wrong measurements and of this resulting damage we refuse any liability. This is a device for quick determination of moisture. The moisture depends on multiple conditions and multiple materials. Therefore we recommend a plausibility check of the measuring results. Each device includes a serial number and the guarantee stamp. If those are broken, no claims for guarantee can be made.

## Notes for measuring shavings

⇒ Weight of shavings must be more than 380g. If you go below that weight you have to compress the shavings in measuring chamber up to 380g.

## Notes

This image shows a blank sheet of white paper with horizontal ruling lines. The lines are evenly spaced and extend across the width of the page. There are no margins, text, or other markings on the paper.

## Self-calibration - fault correction

If the values of the self-calibration exceed a certain limit, the procedure is stopped for reasons of safety.

For this fault, a pollution of the contacts at the bottom of the measuring chamber may be responsible. In this case slightly sand the stainless steel contacts (marked in blue on the picture) using 400 grade abrasive paper. Afterwards the contacts have to be cleaned with alcohol.



If after that procedure the self-calibration is still not successful, please contact Schaller GmbH.

**Note:** *For the self-calibration the measuring chamber has to be empty and cleaned!*

## Instructions for transport

If the humimeter BMA is transported or shipped, the measuring chamber has to be removed from the BMA device.

Otherwise all warranty claims will be rendered invalid.

## Technical data

<b>Resolution</b>	0.1% water content
<b>Measuring range</b>	5 to 70% water content (dependent on the material)
<b>Operation temperature</b>	0°C to +50°C
<b>Storage temperature</b>	-20°C to +60°C
<b>Temperature sensor</b>	infrared (non-contact)
<b>Temperature compensation</b>	automatic
<b>Power supply</b>	100-240 VAC, 1 A, 50-60 Hz
<b>Plug</b>	schuko plug as per CEE 7/7
<b>Display</b>	128x64 matrix display lighted
<b>Dimensions (BxTxH)</b>	432 x 282 x 862 mm
<b>Weight</b>	approx. 26 kg (with measuring box)
<b>Degree of protection</b>	IP 40
<b>Scope of delivery</b>	<b>humimeter BMA</b> BMA measuring box (12 litre) power supply unit 12 VDC, 4 A 2 pieces bucket, 13 litre
<b>Options</b>	determination of bulk density and bone dry weight (atro) USB data interface module integrated printer for BMA rechargeable batteries measuring device check

# !IMPORTANT! Please read

## Most common reasons for incorrect measurements


- **Product temperature out of application range**  
Material **below 0°C** resp. **above +50°C** may cause faulty measurements.
- **Measuring material is frozen or mixed with snow**  
In these cases the accuracy is decreasing heavily.
- **Wrong calibration curve**  
Before starting a measurement please double-check if you have chosen the right calibration curve (material).
- **Wet or mouldy material**  
In this case the accuracy may decrease.
- **Moisture measurement of barks**  
In case of uneven shape of barks in comparison of wood chips, the accuracy may decrease.
- **Wrong filling quantity**  
Ensure that the measuring box is filled with material completely; there must not be less neither more material in it.
- **Wrong filling procedure**  
Place the measuring box on the floor and pour the material into it. Use delivered bucket for that action at every time.

## Device maintenance instructions

To provide a long life of your device please do not expose it to strong mechanical loads, extreme heat, rain and heavy dust.

The weighing plate (grey plastic plate at the bottom of the BMA) has to be free from wood chips and dirt. In case of pollution please vacuum-clean the weighing plate.

*Mind the golden contacts, they must not be touched!*



At the bottom of BMA housing is a cover plate for cleaning screwed. You can remove that and vacuum-clean inside. Clean the measuring box using a **dry cloth or a soft brush**. Any kind of wet cleaning and any use of cleaning powder may damage the device. The **device and the measuring box are not rainproof**, keep them in dry areas!